

Hunters Point Naval Shipyard




Parcel F Radiological Data Gap Investigation (RAD DGI), Phase 2b BCT Meeting February 28, 2013



Parcel F Overview







HPNS Parcel F RAD DGI



- Completed offshore sediment coring at 141 locations along entire length of Parcel F.
 - Based on re-analyses of 8 Phase 1 cores (all below PALs), resampling at those locations (including associated step-outs) were not needed.
- Clam (*Macoma nasuta*) recovery at 5 locations within Parcel F and 2 reference locations in the Bay (Oyster Point and Paradise Cove) were completed.
- Sedflume samples were collected on February 11, 2013.
 Sediment samples were submitted for radiological analyses prior to offsite release. Sedflume evaluation is pending receipt of radiological results.



Sample Collection Activities on Barge








Berths North Area Sample Locations







Berth South Area Sample Locations








South Basin Area Sample Locations








Submarine Area Sample Locations







HPNS Parcel F RAD DGI



SCHEDULE

- Currently waiting on analytical results.
- Sample collection December 10, 2012 to February 14, 2013.
- Laboratory analysis complete* March 8, 2013
- Navy Internal Draft Tech Memorandum April 26, 2013
- Draft Tech Memorandum June 26, 2013
- Final Tech Memorandum July 9, 2013
- *Sedflume evaluation within 30 days of lab analyses.